Application to Amend the Service Authority Jurisdictional Area



Project Name: 3756 Richmond Road,	Keswick VA	,		
Tax map and parcel: 079A1-00-0B-02700, 2500, 25A0		Magisterial District: Scottsville	Zoning: F	Rural Areas
Physical Street Address (if assigned): 375	6 Richmond Road			
Location of property (landmarks, intersection				
Corner of Moose Lane and Richmor	nd Road, Keswick, VA			-
ntact Person (Who should we call/write cor	ncerning this project?): Ge	arrett M. Smith, Agent for Owne	r and Applicant	
		City Charlottesaville		
Daytime Phone () (434) 220-7	735 Fax # ()	E-mail gsmithe	@resortscompa	nies.com
vner of Record Southern Property Man	nagement & Maintena	nce, LLC		
Address 610 West Rio Road		City Charlottesville	State VA	Zip 22901
Daytime Phone () (434) 220-7	712 Fax # ()	E-mail dicedo	om666@gmail.	com
plicant (Who is the Contact person represen	ting?): Southern Prope	erty Management & Maintenand	e, LLC	
Address 614 West Rio Road			State VA	
Daytime Phone () (434) 220-7	7727 Fax # ()	E-mail tbbuon	o@embarqmail	.com;

Fee Amount \$_____ Date Paid

Receipt # ____Ck#__

Jurisdiction area designation requested		
Water and Sewer ✓ Water Only to existing structure(s)		
Water Only		
Limited Service (Describe in justification below)		
Current Service Area Designation		
No designation		
		
Water Only Water Only		
Limited Service (Please describe		_)
Justification for request:		
See September 4, 2015 letter from Virginia Department of Health Office owner concerning the status of the existing water supply.	ce of Drinking water to a representative of the former	r
See March 3, 2022 Cardno/Stantec report of Vincent Day and Bryan I investigated, obtaining an adequate groundwater well is unlikely, and such as obtaining a connection to public water.	all alternate source of water would be more years.	
See May 25, 2022 report of drilling by Matheny Well Drilling and Serv reported or water found.		-
This is a large facility and we requires a public water supply for any uwells, and proximity to an ACSA connection point make this property Albemarle County Service Authority. The property is directly across f	SUITABLE TO ALL EXPANSION OF THE PARTY OF TH	the
*		
Owner/Applicant Must	Read and Sign	
I hereby certify that the information provided on this application	on and accompanying information is accurate, tr	ue
and correct to the best of my knowledge and belief.		
	6/13/2022	
Signature of Owner Contract Purchaser, Agent	Date	
Signature of Owner, Constact 1 dichases, 13gon		
Garrett M. Smith, PLLC , Agent	(434) 220-7735 Daytime phone number of Signatory	
Print Name	Revised 7/1/2021 Page	e 2 of 2



COMMONWEALTH of VIRGINIA

Marissa J. Levine, MD, MPH, FAAFP State Health Commissioner DEPARTMENT OF HEALTH
OFFICE OF DRINKING WATER

John J. Aulbach II, PE Director, Office of Drinking Water Lexington Field Office

131 Walker Street Lexington, VA 24450 Phone: 540-463-7136 Fax: 540-463-3892

September 4, 2015

SUBJECT: Albemarle County
Waterworks - Charlottesville Moose Lodge

Mr. Steve Shifflett 2412 Troy Road Troy, VA 22974

Mr. Shifflett:

Thank you for your participation in the meeting held on August 27, 2015, at the Charlottesville/Albemarle Health Department concerning the Charlottesville Moose Lodge water system.

As you are aware the Charlottesville Moose Lodge Waterworks Operation Permit was recently revoked due to ongoing unaddressed compliance issues; this action also resulted in the revocation of Local Health Department permits for food service. The Waterworks Operation Permit revocation was the end result of a long history of enforcement actions resulting from continued non-compliance with the Commonwealth of Virginia Waterworks Regulations. Following is a summary of violations and enforcement actions:

- VDH issued 121 separate water quality and monitoring violations since the facility was originally issued a Waterworks Operation Permit in May 2003
- The USEPA issued a "Notice of Violation and Request for Information" dated January 2015
- State Health Commissioner Special Order No. 11-2014-10 issued January 5, 2015
- State Health Commissioner Special Order (and permit revocation) No. 06-2015-05 disused July 28, 2015

The non-compliance history of the Charlottesville Moose lodge water system indicates serious issues related to the available quantity of water, the quality of water delivered to consumers, and the technical, managerial and financial capability necessary to protect public health. As such, the following initial steps must be taken if the Charlottesville Moose Lodge wishes to have their facility permitted again by this office.

- A licensed Virginia professional engineer must be contracted to evaluate the existing water system and submit a report with recommendations for improvements or additions to the water system to meet requirements of the Commonwealth of Virginia Waterworks Regulations. The engineer's report must address the fact that:
 - Continued use of the existing side-stream in-ground concrete storage tank cannot be allowed.
 This tank has shown that it is susceptible to entry by tree roots and the existing access hatch could easily allow for contamination by rodents, insects and other debris.



Mr. Steve Shifflett Page 2 of 2

> SUBJECT: Albemarle County Waterworks - Charlottesville Moose Lodge

- ii. Continued use of the existing wells cannot be allowed. Of the four drilled wells on site, construction records are only available for the two newest wells. These two wells do not meet the Waterworks Regulations minimum construction requirements due to a combination of shallow well casings and unknown grouting. These existing wells have a history of raw water quality high in Total Coliform bacteria and periodic contamination of E. coli. In addition, the reliability and capacity of the existing wells is poor as evidenced by frequent mechanical failures, low yields and water hauling to supplement their output.
- We will review and evaluate recommendations contained in the required engineer's report. Before VDH
 can consider issuing a Waterworks Operation Permit the Charlottesville Moose Lodge will be required to:
 - Satisfactorily address any items contained in the approved engineer's report including any required improvements or additions to the water infrastructure.
 - Secure an acceptable water source that is capable of providing adequate quantity and quality of water and meeting all applicable requirements of the Waterworks Regulations.
 - Provide a contract operator holding a minimum Virginia Class 6 Waterworks Operator license to oversee and operate the system, and;
 - iv. Establish an escrow account with sufficient funds deposited to cover the costs of all required water quality monitoring and the costs of the contract operator for a period of two years.

If you have any questions about these requirements please do not hesitate to contact Steve Kvech, PE, District Engineer, at (540) 463-0424.

Sincerely,

James W. Moore III, PE Engineering Field Director

JWM/SJK/kl/150904_1

cc: Charlottesville Moose Lodge -- Atm: Mr. Dale Mullins
Albemarle County Building Official -- Mr. Jay Schlothauer
Albemarle County Executive -- Mr. Thomas C. Foley
VDH -- OEHS -- Atm: Ms. Julie Henderson
Mr. John McClelland, Environmental Health Manager
Albemarle County Health Department -- Atm: Dr. Denise Bonds, MD, MPH
VDH -- ODW Richmond Central -- Atm: Mr. Robert Payne, JD



now



Cardno now Stantec

10988 Richardson Road Ashland, VA 23005 USA

Phone: 804 798 6525

www.cardno.com

March 3, 2022

Mr. Trevor Hammer Southern Property Management & Maintenance 510 Nottingham Road Charlottesville, VA 22906

Summary of Groundwater Resources - Former Charlottesville Moose Lodge Parcels 79A1-B-24, 79A1-B-25, 79A1-B-27, Albemarie County, Virginia

Dear Mr. Hammer:

The former Charlottesville Moose Lodge property (the property) has had a history of poor water quality and well yields which have affected the ability of property owners to provide water to users of the property. In late 2021, Cardno now Stantec was engaged to identify potential drilling targets and obtain Virginia Department of Health (VDH) well site approvals. In February 2022, a well was drilled at one of the selected locations and yielded no water. The purpose of this memorandum is to present our professional opinion on the feasibility of operating an onsite groundwater supply system based on existing documentation and knowledge of the property's water system and the hydrogeologic setting.

Water System History

The property's water system has historically sourced water from four (4) groundwater wells (Figure 1). Well construction information presented below was obtained from the Charlottesville Moose Lodge Virginia Department of Health (VDH) Engineering Description Sheet for VDH Waterworks Operation Permit (WOP) #2003203 (2006; Attachment 1).

Well 1 was constructed in 1972, is 300 feet deep, and reportedly yielded 1.5 gallons per minute (gpm) at the time of construction. Steel casing extends to 20 feet below land surface (bls).

Well 2 was constructed in 1988, is 300 feet deep, and reportedly yielded less than 1 gpm at the time of construction. PVC casing extends to 20 feet below land surface (bls).

Well 3 and Well 4 were installed at an unknown time prior to 1972. Well construction information below land surface is unknown, but both wells are reported to have a "very low yield".

On July 28, 2015, VDH revoked the property's WOP, citing continually poor water quality and low well yields, among other concerns (Attachment 2). One of the requirements for issuing a new WOP was to "secure an acceptable water source that is capable of providing adequate quantity and quality of water...".

In February 2022, Well 5 (Figure 1) was constructed. The well is 400 feet deep and reportedly yielded no measurable water.

Hydrogeology

Beneath the property, a relatively thin layer of soil and saprolite (in-situ weathered bedrock) overlies Candler Formation phyllite and schist bedrock of Cambrian age (1993 Geologic Map of Virginia, Virginia Division of Mineral Resources). Candler Formation groundwater flow is almost entirely limited to areas of hydraulically connected secondary porosity, created by faulting and fracturing of bedrock. Wells constructed in fractured-bedrock aquifers only yield sustainable quantities of water if they intersect fractures which 1: contain water, and 2: are hydraulically

Australia • Belgium • Canada • Colombia • Ecuador • Germany • Indonesia • Kenya • New Zealand • Nigeria • Papua New Guinea • Peru • Philippines • Singapore • United Arab Emirates • United Kingdom • United States • Operations in over 100 countries 2

March 3, 2022 Mr. Trevor Hammer Summary of Groundwater Resources - Former Charlottesville Moose Lodge Parcels 79A1-B-24, 79A1-B-25, 79A1-B-27, Albemarle County, Virginia



connected to a source of recharge, such as the land surface or the bedrock contact with soil or saprolite (through the infiltration of precipitation).

In 2003, ENSAT Corporation and Albemarle County prepared a Groundwater Availability and Sensitivity Assessment with Proposed Groundwater Assessment Standards as part of the Albemarle County Hydrogeologic Assessment Report. Of note in this report is that the Candler Formation is "generally more ductile than other rocks in the County, meaning that fractures can close up due to the weight of overlying material". A result of this is a decreased likelihood of wells intersecting water-bearing fractures. This fact, in conjunction with other analyses, resulted in the Candler Formation being categorized as having the "Lowest Relative Availability" of groundwater.

Conclusion

Five (5) wells have been constructed on the 6-acre property, none of which yield water of sufficient quantity and quality for the property's former use ("clubs and lodges" by Special Use Permit), the proposed by-right use ("religious assembly of not more than 200 persons"), and other non-residential by-right uses. Excluding the development footprint and drainfield areas, the area available for wells is less than 5 acres. The wells are each 100 feet or more from each other, spatially covering a large portion of the property, and are located on differing slope aspects, topographic features, and elevations. Obtaining groundwater from the Candler Formation is well-known to be a challenging and uncertain process.

Given the evidence of poor water quality and yield from the property's existing wells and the geology, it is our opinion that the property has been sufficiently investigated, obtaining an adequate groundwater well is unlikely, and an alternate source of water would be more feasible, such as obtaining a connection to public water.

Please feel free to contact us if you have any questions.

Sincerely.

Vincent Day, PG Senior Hydrogeologist

for Cardno now Stantec Direct Line: +1 804-368-1003


Email: Vincent.day@cardno.com

Bryant Mountjoy, PG Project Hydrogeologist for Cardno now Stantec

Direct Line: +1 804-412-6546

Email: bryant.mountjoy@cardno.com

Garrett Smith (gsmith@resortscompanies.com) CC: Minor Smith (minor.smith@longandfoster.com)



Commonwealth of Virginia Uniform Water Well Completion Report

Owner: Southern Property Mnsmt. (i Maint., LLC	Tax Map ID
ddress: P.O. Box 7505		VWCB Permit
Charlottesville, VA 22906		VWCB ID
hone:	a Blacca Ladas	County Albemarie
ocation: formerly the Charlottesvill	e Modes Louis	Work)
	* Well Data *	
waster 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Seneral Information	to the second	Total Depth of well 405ft
orilling Method Rotary	Date Completed 2/24/2022 Vield 1/10 (GPM)	Length of Test 1 hour
Depth to Bedrock 266t	Yield 1/10 (GPM) Stabilized Water Level	Natural Flow (Rate)
Static Water Level 8ft	Disinfectant Used	Amount Used
Well Disinfected (Y or N)	Distillectant osed	
eval		
Casing From +2ft to 54ft	From to	From To
Size 6 % Material PVC	Size Material	Size Material
Weight/schedule	Weight/Schedule	Weight/Schedule
Gravel Pack		
[발문사회 : 12]	From to	Fromto
From to		
Grout	From To	From to
From 0 to 50%	Bore Hole Size	Bore Hole Size
Bore Hole Size 10 inch.	A PARAMETER STATE OF THE STATE	Type
Type_cement	Туре	Method
Method Pumped	Method	Wileday Va
Water Zones or Screened Intervals		From To
Fromto	FromTo	
Mesh Size Diam	Mesh SizeDiam	
FromTo	FromTo	From To
Mesh SizeDiam	Mesh SizeDiam	Mesh SizeDlam
	12 12 12 12 12 12 12 12 12 12 12 12 12 1	Signature State (Section 1988)
	Use Date	er Sagar va er er
		Adouthoding
Private well: Dom	estic_X Agricultural	Industrial Monitoring
Public well: Com	nunity Non-community	
	Abandonment Infor	mation
	7	
Bored of Dug Wells	V	Vells other than Bored Wells
Casing Removed, Y or N?	C	asing removed, Y or N?
If Y, Depth to which casing was rer	noved	Depth to which casing was removed
Depth and Type of Fill:	A	Applicable, depth(s), and type of gravel/sand fill:
	S	ource of gravel or sand:
Source of Fill		Cement: From To From To

°D:	filer	s Lo	HZ*

	"Drifters Log"	
Depth	Description of Formation or Sediment	Remarks
0.26		
0 – 26	dirt, soft rock	~ Tertions
26 – 405	gray rock	Op-waterfight cap
		d b
		11 11 00 85. 5
		1 Sorting gravi
		Cemora
		1 1 -10 cm 50F 2
		54+ casing
		soft. growt cemera growt soft soft 2 pvc cosing
		1 54
		105 FT.
		3
		,
	(Use Additional Sheets if necessary)	
: "		
I certify that the information of	ontained here is true and that this well was installed and constr	ucted in accordance with the
permit and further that the we	ell complies with all applicable state and local regulations, ordina	ances and laws.
Name Adathany Wall Drilling	and Dum Condet Inc	
Name <u>Matheny Well Drilling</u> Address <u>2797 Kacey Lane</u>	and Fullip Selate, Inc.	
Afton, VA 22920		
Phone 434-760-4090		
	. AM. H	
Drillers Signature Number		
Date 5/25/2022	Representing	

Virginia Contractors License Number 017282 & 2719000083